

Star of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program

August 14, 2006



Mine Name:	Cotton Thomas Quarry				
Operator Na	me:	Star	Stone	Quarries,	Ind

Permit number: M0030024 Inspection Date: August 8, 2006

Time: 8:30 am

Inspector(s): Lynn Kunzler, DOGM

Other Participants: Lon Thomas, Tyler Thomas, Vic Jackson, Rex Larsen, Tiffany Larsen

Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	\boxtimes	\boxtimes	
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages / Erosion Control	$\overline{\boxtimes}$		
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Concurrent Reclamation			
7. Backfilling/Grading (trenches, pits, roads,			
8. Soils		\boxtimes	
9. Revegetation	\boxtimes		
10. Other			

Purpose of Inspection:

Inspection was performed at the request of the operator to inspect past reclamation to determine if revegetation success standards were achieved.

Inspection Summary:

- 1. This site was active at the time of the inspection. The Division had recently approved a permit amendment to add the Chocolate Charcoal Pit. Work on this area has aleady begun with hand collection of surface stone. Construction of the access road began yesterday.
- 8. While the amendment for the Chocolate Charcoal Pit did not include a request for salvaging topsoil, this should have been done. Even though there was significant vegetation (approximately 40% ground cover), most of it was rooted in the cracks between the rocks. Efforts to salvage the minute amount of soil material would be nearly impossible.
- 9. Five areas were requested to be inspected for reclamation success and full bond release of the areas. The Camp area, the original access road, the South Granite pit, the West Granite Pit and the East Granite Pit. The camp area was proposed for use as a staging area for the post mining land use. The only remaining item from the past mining activity is a damaged trailer house. The original access road had mixed results. The regrading was great, with the area being left in a roughened condition. There were no signs of erosion in instability. Vegetation on the first ¼ of the length and a couple of small (50-100 segments) was satisfactory. However, the majority of the road was infested with cheatgrass and thistle (desirable vegetation was very sparse). The South Granite pit had and average of 65% ground cover. The surrounding area had a ground cover of 75%. The West Granite had a vegetation cover of 46%. The surrounding area had a

Inspection Date: August 8, 2006; Report Date: August 14, 2006

Page 2 of 2 M0030024

vegetation cover of 65%. The East Granite area had a vegetation cover of 40%. The surrounding area had a vegetation cover of 50%.

Conclusions and Recommendations:

- 1 & 8. The operator will request a variance to not salvaging soil for the Chocolate Charcoal Pit when the Plan revision is submitted. This variance should be approved.
- 9. Cleanup of the camp area needs to be completed before this area is released. The operator will spot spray the thistle this week (in rosette stage) and will apply Plateau in the fall to control the cheat grass. The areas dominated by weeds will be reseeded. Vegetation establishment of the three granite pits is considered successful and has exceeded the 70% revegetation success standard. It is recommended that these three sites be released.

Continue to monitor the site when in the area.

Photos were taken to document site conditions.

Inspector's Signature

LK:pb

O:\M003-BoxElder\M0030024-CottonThomas\inspections\Insp-08082006.doc

Date: August 11, 2006